



TEST DETAILS:

1234 Sample Drive

Sandusky, OH 44870
Erie

Sample Client
419-503-3644
info@sanduskybayinspections.com

Test Start Date/Time: Saturday, October 07, 2017 // 12:00 PM

Test End Date/Time: Monday, October 09, 2017 // 12:00 PM

Location of Instrument: Basement

Notes: This is the report of the radon screening measurement that was conducted at the above address. The measurement was performed using a RadStar RS800 continuous radon monitor (CRM) and was performed in conformance with the test protocols established by the US Environmental Protection Agency and in Ohio Revised Code 3723 and Ohio Administrative Code 3701-69.


During the measurement period radon gas measurements were recorded once every hour during the entire period. The Overall Average concentration of radon during test period was: 1.4 pCi/L. The radon gas measurement was completed and there is no evidence that the CRM was tampered with in any way. Therefore the average values contained in this report reflect the radon gas concentration at the time of the test and should not be construed as either predictive or supportive of a similar measurement conducted at another time in the same structure.

Based on the results from this test mitigation is not required.

TEST RESULTS:

Average: 1.4 pCi/L

Test ID# 80317



Scott Eckert
 Certification #:
 License 1:
 License 2:

Date
 Ohio
 RT1258



INTERVAL REPORT:

Hour	T	B	AC	pCi/L	Temp	Humd	Alpha
1			*	1.5	63	56	48
2			*	1.5	63	56	47
3			*	1.3	63	56	40
4			*	0.8	63	58	26
5			*	1.2	64	58	37
6			*	0.8	65	59	25
7			*	1.6	65	60	51
8			*	1.1	65	60	35
9			*	0.6	65	61	19
10			*	0.8	65	60	27
11			*	0.2	65	58	9
12			*	0.6	64	57	19
13			*	0.9	64	58	28
14			*	1.0	64	57	31
15			*	0.8	64	58	26
16			*	1.4	65	58	44
17			*	1.5	65	58	48
18			*	0.8	65	57	25
19			*	1.2	65	58	38
20			*	1.3	65	59	40
21			*	2.0	66	59	63
22			*	2.1	65	59	67
23			*	2.6	65	59	80
24			*	1.5	64	59	46
25			*	2.0	64	60	63
26			*	1.5	64	60	48
27			*	1.8	64	60	56
28			*	2.1	63	60	66
29			*	1.9	64	59	59
30			*	1.3	64	60	41
31			*	1.6	64	61	49
32			*	1.4	64	60	45
33			*	1.3	64	60	40
34			*	1.0	64	59	32
35			*	1.0	64	58	31
36			*	1.1	64	57	36
37			*	1.1	64	58	36
38			*	1.0	64	57	32
39			*	1.5	64	58	47
40			*	1.1	64	58	34
41			*	0.8	65	57	27
42			*	2.0	65	58	64
43			*	2.5	65	58	78
44			*	1.7	65	58	54
45			*	2.5	65	58	78
46			*	2.4	65	58	75
47			*	3.2	65	58	100
48			*	2.1	65	59	66

Minimum: 0.2 pCi/L **Maximum:** 3.2 pCi/L **Average:** 1.4 pCi/L

Scott Eckert	Date
Certification #:	Ohio
License 1:	RT1258

Scott Eckert
Sandusky Bay Inspections LLC
609 Parkland Dr.
Sandusky, OH 44870 Erie
Phone: 419-503-3644 Fax:
seckert@sanduskybayinspections.com



License 2:

RadStar RS800
Serial#: 01814

Radon Detector/Monitor
Calib.#: 00335 Bkgnd13 Test ID#: 80317

Version 1.6
Page 4 of 4